



Attorney Docket No. 1349.1332
cjc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Jeong-Seon KIM, et al

Application No.: 10/706,953

ATTENTION

Confirmation No.: 7774

CERTIFICATE OF CORRECTION

Filed: November 14, 2003

BRANCH

U.S. Patent No.: 7,040,739

Batch No.:

Issued: May 9, 2006

For: FLEXIBLE PRINTED CIRCUIT BOARD

REQUEST FOR CERTIFICATE OF CORRECTION

*Certificate
SEP 11 2006
of Correction*

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Sept. 6, 2006

By: 
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

09/07/2006 SDENBOB1 00000080 7040739

01 FC:1811

100.00 OP

SEP 12 2006
60000

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 7,040,739

DATED : May 9, 2006

INVENTOR(S) : Jeong-Seon KIM, et al

Column 9, Line 28, after "provided" change "alone" to --along--.

Column 9, Line 54, after "provided" change "alone" to --along--.

Column 11, Line 18, change "lines" to --line--.

Column 11, Line 19, change "lines" to --line--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,040,739

No. of add'l copies
@ 50¢ per page

⇒

SEP 12 2006
MAIA